ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	3	Alturu
Street ID	**Street Name**	**Significant Landmark**
W1065, I1089, W1063, W1293, W0734, W1289	NA, 2nd Crs	Basavalingappa layout
Segment No.	**Total Length (m)**	
3/C-W1065/S044310	50.04	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	7.72	77.545990	13.085711	77.546060	13.085726	W1289	W1289
2	5.43	77.542729	13.087585	77.542764	13.087550	W1065	W1065
3	36.89	77.542586	13.087692	77.542827	13.087457	W1063	W1065

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of Concrete Drain and Concrete Roads at Basavalingappa layout in wards no 03 Yelahanka Satellite Town Sub division Yelahanka zone	602000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	Construction of Concrete Drain and Concrete Roads at Basavalingappa layout in wards no 03 Yelahanka Satellite Town Sub division Yelahanka zone	003-16-000031
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE (YNK.D) /WO/105/2016 -17	07/01/2017	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
27/02/2017	26/02/2018	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	

)449863065

Field Inspection Details

Number of Trees	Any Other Information	Name
0		CHANDRAKANTH
Date of Inspection	**Remarks**	
19/03/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Alturu **Street ID:** W1065, I1089, W1063, W1293,

Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	19/03/2017	18/04/2017	COMPLETED
SE	VASU K M	19/03/2017	18/04/2017	COMPLETED
EE	VASU K M	19/03/2017	18/04/2017	COMPLETED
AEE	ASHOK	19/03/2017	18/04/2017	COMPLETED
AE	CHANDRAKANTH	19/03/2017	18/04/2017	COMPLETED
AE	CHANDRAKANTH	19/03/2017	18/04/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Alturu **Street ID:** W1065, I1089, W1063, W1293,